






## **APPENDIX B: DETAILED NOISE MEASUREMENT RESULTS**



**Figure B-1 Measured Hourly Noise Levels, Site 1**
















**Figure B-2 Measured Hourly Noise Levels, Site 2**


















**Figure B-3 Measured Hourly Noise Levels, Site 6**
















**Figure B-4 Measured Hourly Noise Levels, Site 7**


















**Figure B-5 Measured Hourly Noise Levels, Site 9**














**Figure B-6 Measured Hourly Noise Levels, Site 10**


















**Figure B-7 Measured Hourly Noise Levels, Site 12**
















**Figure B-8 Measured Hourly Noise Levels, Site 15**

















**Figure B-9 Measured Hourly Noise Levels, Site 18**









**Figure B-10 Measured Hourly Noise Levels, Site 19**

